

DEPARTMENT OF CONSERVATION
STATE OF LOUISIANA

SWD

PLUG AND ABANDON REPORT

DATE WORK DONE 12-28-70

WELL SERIAL NO. _____
WORK PERMIT NO. L#2584-70

LAFAYETTE DISTRICT
(Three Copies to be Filed with the District Office)

NOTE: This Report Will be Returned if Not Properly Completed And Signed.

Field ANSE LA BUTTE Parish S.T. MARTIN Sec. 121 Twp. 9S Rge. 5E

Company PAN AMERICAN PETROLEUM CORP Lease ANSE LA BUTTE SWD Well No. 1

Total Depth 1250 Condition of Well UNSUITABLE FOR REPAIR

- 1. Surface Casing Size _____ Depth _____ Amount Pulled 0
- 2. Protection Casing Size _____ Depth _____ Amount Pulled _____
- 3. Production Casing Size 6-5/8 Depth 1250 Amount Pulled 0

CEMENT PLUGS

- 1. Depth 992 To 789 No. of Sacks 40 How Placed DISPLACED
- 2. Depth 56 To 6 No. of Sacks 8 How Placed POURED
- 3. Depth _____ To _____ No. of Sacks _____ How Placed _____

Mud Record: Weight S.W. Viscosity _____

Remarks: CASING CUT 6' BELOW GROUND
LEVEL. STEEL PLATE WELDED ON TOP

This work was done according to the Rules and Regulations of the Department of Conservation.

Bull [Signature]
WITNESS

PAN AMERICAN PETROLEUM CORP.
COMPANY

[Signature]
(Signed) REPRESENTATIVE